

High Pressure Cleaning




25 Mar 2020 / ABS

Complete

Inspection score	Failed items	Created actions
100%	0	0
Conducted on 📅 25th Mar, 2020 ⌚ 5:55 PM GMT		
Prepared by ABS		
Location Unanswered		


Before Areas

100%

Please provide photos of the areas prior to cleaning		Yes		
— Photos				
				
Photo 1	Photo 2	Photo 3	Photo 4	Photo 5
				
Photo 6	Photo 7			

During Cleaning

100%

Please provide photos of the area during cleaning	Yes
— Photos  Photo 8  Photo 9  Photo 10  Photo 11  Photo 12  Photo 13	

After Cleaning

100%

Please provide photos of the area after cleaning	Yes
— Notes We pressure cleaned 2187 square metres of block paving.	




Sanding

100%

Have the areas been sanded	Yes
— Notes We sanded 2187 square metres of block paving. — Photos  Photo 14  Photo 15  Photo 16  Photo 17  Photo 18  Photo 19	

Rainwater Gullies & Outlets

100%

Have gullies and outlets been cleaned		Yes
— Notes We cleared 55 metres of rainwater gullies. — Photos  Photo 20  Photo 21  Photo 22  Photo 23  Photo 24  Photo 25  Photo 26		




Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 20



Photo 19



Photo 22



Photo 24



Photo 21



Photo 26



Photo 23



Photo 25