



Window Cleaning

24 Apr 2020 / ABS

Complete

Score	100%	Failed items	0	Actions	0
Conducted on		24th Apr, 2020 10:22 AM BST			
Prepared by		ABS			
Location					

Window Cleaning

100%

Is the TDS reading between 0-5

Yes



Photo 1

Are the correct safety signs put out

Yes



Photo 2

Have all reachable windows been cleaned

Yes

Bird dropping removed off window




Photo 3



Photo 4



Photo 5



Photo 6




Photo 7




Photo 8

Have all reachable frames been cleaned

Yes

Have all ground floor window ledges been wiped

Yes



Photo 9



Photo 10



Photo 11

Are there any broken windows to report

N/A

The windows sills have green algae on which can't be cleaned from the ground, ladders will be needed




Photo 12



Photo 13




Photo 14



Photo 15

Appendix



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7




Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15